

Client

Charles R Palanzo

Service Location

846 Iron Latch Road, Franklin Lakes, NJ 07417



Report Date

03/02/2021

Prepared by

Joe Electrician

Organization

Acme Electric
12 Main Street, Yonkers, NY
914-335-2600

Site Details

Site Description	Multi-story private residence with standard 3 phase 110-120 v electrical service
General Condition	Generally all circuits in good condition, certain basement circuits have no earth ground.
Safety Analysis	After repair of faulty GFCI the premise is regarded as Safe

Electrical Service Details

Attic Fan Outlet	02/28/2020 10:04 AM	Correct Wiring	GFCI Unknown
Bathroom 1 OH lights	02/28/2020 10:10 AM	No Power Open Circuit	GFCI Unknown
Bathroom 1 Sink Outlets	02/28/2020 10:04 AM	Correct Wiring	GFCI Unknown
	02/28/2020 10:06 AM	Correct Wiring	GFCI Fail
	02/28/2020 10:16 AM	Correct Wiring	GFCI Pass
Bedroom 1	02/28/2020 10:16 AM	Correct Wiring	GFCI Unknown
Bedroom 2	02/28/2020 10:16 AM	Correct Wiring	GFCI Unknown
Bedroom 3	02/28/2020 10:16 AM	Correct Wiring	GFCI Unknown

Electrical Service Details			
Mast BR Floor Outlets	02/28/2020 10:16 AM	Correct Wiring	GFCI Unknown
Mast BR Alt Outlets	02/28/2020 10:16 AM	Missing Neutral	GFCI Unknown
Master Bathroom Outlets	02/28/2020 10:16 AM	Correct Wiring	GFCI Pass
Master Bathroom Lights	02/28/2020 10:16 AM	No Power Open Circuit	GFCI Unknown

Breaker Panel: Main Panel		Location: Basement west side	
1	Mast BR Floor Outlets	2	Bedroom 3
3	Mast BR Alt Outlets	4	
5		6	
7		8	Master Bathroom Outlets
9		10	Master Bathroom Lights
11	Bathroom 1 OH Lights	12	
13		14	Bedroom 1 Bedroom 2
15		16	
17		18	
19		20	

Breaker Panel: Sub Panel		Location: Beneath Main Panel	
1	Attic Fan Outlet	2	
3	Bathroom 1 Sink Outlets	4	
5		6	
7		8	
9		10	



Circuit Navigator
www.circuitnavigator.com

Get the App!